	**	Approved For Release 2002/	08/21 SCHAIRDY	89B00569R000	0030066-4	na majanda katalan da katalan katalan ROUTING:		
	DATE	1914Z 12 DEC 60 T	-tur Jeuri		l ps	15		
		17142 12 DEC 69)		RE!	DB	6		
	erren eta ena enquesta como esperante por es	ting an engagement (an engagement of the contract of the contr	reparation and section is automobility for a surface of a property of the section	To be a second				
25X1A	TO	DIRECTOR		Date By				
	FROM		ACTION ROR TION TAKEN	1/2	Part and State Sta			
	ACTION	DPD (1-2-3-4-5-6-7-8-1-4-5-6-7-8-1-4-6-6-6-7-8-1-4-6-6-6-7-8-1-4-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6	TION DEFERRED	TOTAL STATE OF THE	ROUTINE			
	NFO	S/C (11)	UNTIL	line line	The first of the state of the s			
		CL Z AC	TION REFERRED					
	Security and additional	TOR: 2012Z 12 DEC 60			T C Sales and the sales and th	IN-38193		
2	5X91A	info			25X1Aite	Ø7 ø		
				DOCUMENT NO.	L			
25	5X1A	FOR		No chance in t Describerie Claber chance				
		REF SORTIE 3016		AUINI na 72	. 1 = 1			
		1. WAS WELL PLEASED W	TTU DDAMTE	DATE 28 Aug 86	REVIEWER	25X1A		
		2. IT WAS NECESSARY T						
		PRIOR TO TAKE OFF EVEN TH						
		CHANNELS THREE HOURS PRIOR	R. BARELY	MADE OUR TA	KE-OFF ON	TIME.		
		3. WAS PARTICULARLY PI	LEASED WITH	THE DRIVER	S PERFORMAN	9CE		
	BASED UPON OUR PRELIMINARY INFORMATION. HE HAS ALSO CONSISTENTLY							
		DONE A GOOD JOB ON RECENT TRAINING SORTIES.						
		4. FLIGHT PLANNING TEAM PREDICTED FUEL WITHIN 4 GALLONS						
		OF ACTUAL FUEL REMAINING						
25X 25X		5. FAILED TO PROPERLY POSITION SWITCH ON						
	, .	WHICH WILL LOSE THE INFORM	ATION ON T	HE COUNT OF	└ 'FRAMES: AN			
		AM VERY DISPLEASED OVER TH				1		
		UPON IN SEPTEMBER DOES NOT						
		am paging of	and the second s	The Later Commence	WALLE WALL	DE VA		

Approved For Release 2002085 C 130 FTDP 89B00769R000300030066-4

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Copy No.

Approved For Release 2002/08/21 : CIA-RDP89B00569R008300030066-4

T ^ ^	_	-	-	\sim	 _
₹ -0-8	ν.	_	, -	$\boldsymbol{\nu}$	 - 1

25X1A	070 (IN 39193)	PAGE 2
• •		
25X1A	CORRECTED IMMEDIATELY. SINCE PERS	OUNEL HAVE CONSISTENTLY
4	POSITIONED THE SWITCH PROPERLY IN THE PA	ST IT HAD NOT COME TO
	MY ATTEUTION AS A DEFICIENCY.	
25X1A	5. E CAPSTAN DRIVE MOTOR FAIL	ED AFTER APPROXIMATELY
	3 PLUS 30 FLIGHT DURATION. CAUSE UNKNOW	n•
	7. THERE WAS ONLY TIME FOR A CURSORY	CHECK OF 25X1A
!	TAKE. AS MEAR AS COULD DE DETERMINED TH	IS SYSTEM OPERATION WAS
İ	SATISFACTORY AND THE TECHNICIAN FOUND AT	LEAST ONE SIGNAL THAT
	HE BELIEVES TO BE OF INTEREST, HOWEVER,	THIS IS AN UNQUALIFIED
	OPINION.	
:	8. THIS EXERCISE HAS BEEN VERY VALUA	BLE IN PROVIDING EXPERIENCE
	AND WE HAVE LEARNED QUITE A BIT BUT WILL	NOT BE SATISFIED
	UNTIL WE HAVE ELIMINATED OR REDUCED TO A	S ARCOLUTE MINIMUM

END OF MESSAGE

9. THE ENTIRE DETACHMENT IS UNANIMIOUS IN THEIR WISHES THAT

ALL FACTORS THAT MAY DETRACT FROM THE MISSION.

THIS SORTIE MAY DE OF VALUE TO YOU.